





Appendix I


Condition of the tiles - stability and salts

	tiles loose
	failed mortar - poor adhesion
	mould
	serious visible salt damage




transport of water through opening/split in upper stone wall


SOUTH SIDE




Panel 8.1




Panel 8.2




Panel 8.3



Panel 8.4




Panel 8,5




Panel 8.6


WEST SIDE




Panel 8.7




Panel 8.8




Panel 8.9




Panel 8.10



Panel 8.11




Panel 8.12




Panel 8.13


Convento de Santo Antônio do Recife, Pernambuco, Brasil, 2010
NORTH SIDE




Panel 8.14



Panel 8.15



Panel 8.16



Panel 8.17

Convento de Santo Antônio do Recife, Pernambuco, Brasil, 2010


	1	2	3	4	5	6	7	8	9	10	11	12	13	14
D	Orange	Orange	Orange	Orange	Orange	Orange	Orange	White	Orange	Orange	Orange	Orange	Orange	Orange
C	Orange	Orange	Orange	Orange	Orange	Orange	Orange	White	Orange	Orange	Orange	Orange	Orange	Orange
B	White	Orange	White	White	White	White	White	White	Orange	Orange	Orange	Orange	Orange	Orange
A	White	White	White	White	White	White	White	White	White	White	White	White	White	White

Panel 8.18


	1	2	3	4	5	6	7
D	Orange	Orange	Orange	Orange	Orange	Orange	White
C	Orange	Orange	Orange	Orange	Orange	Orange	Orange
B	White	Orange	Orange	Orange	Orange	Orange	Orange
A	White	White	White	White	White	White	White

Panel 8.19


EAST SIDE




Panel 8.20




Panel 8.21




Panel 8.22




Panel 8.23



Panel 8.24



Panel 8.25



Panel 8.26